Consulting Structural Engineers



STRUCTURAL_SOUNDNESS_CERTIFICATE

This is to certify that the premises Fusion International School, Ground + 2 floors of Total BUA - 40,000 Sq.Ft. in land of 9,200 Sq.Yds. Bearing Survey no. 383, Ameenpur, lingampally. Patancheru Mandal, S anga Reddy dist, Telangana state are running the School for Classes from Nursery - Grade 10.

The school is affiliated to CBSE, Affiliation no. 363

I had visited the building. It is Structurally Sound and Safe (all the columns & beams are structurally strong and are in good condition). This building is having sufficient number of rooms, are in Sound, Lighted and Ventilated condition. The above Premises are as per the present condition Structurally Sound and Safe as on date.

This certificate is invalid, if any subsequent modifications are made to the structure in any manner.

KALAKOTI VIJAYA KUMAR
550IAIEngineerITP10IGHMCI2021-26

Date: 27-11-2024 Place: Hyderabad